SAFETY DATA SHEET

EP[™] 100 "B" Component Revised Date: 08/13/2019 Version: 7 SDS-276

SECTION 1: IDENTIFICATION

PRODUCT NAME CAS NUMBER PRODUCT USE MANUFACTURER ADDRESS PHONE FAX EMERGENCY CONTACT TOLL FREE INTERNATIONAL FAX EP[®] 100 "B" Component Not available Polyurea Coating Specialty Products, Inc. (SPI) 2410 104TH ST. CT. S. STE D LAKEWOOD, WA 98499 253 588 7101 800 627 0773 253 588 7196 FOR SPILLS, LEAKS, FIRE, OR EXPOSURE CALL CHEMTREC 800 424 9300 +1 703 527 3887 913 321 1490

SECTION 2: HAZARDS IDENTIFICATION

GHS LABEL ELEMENTS GHS PICTOGRAM





DANGER

DANGER					
GHS CLASSIFICATION					
CATEGORY			HAZARD STATEMENTS		
Acute toxicity dermal		Category 4	H312	Harmful in contact with skin.	
Skin sensitization		Category 1	H317	May cause an allergic skin reaction.	
Serious eye damag	ge/eye irritaion	Category 1	H318	Causes serious eye damage.	
Respiratory sensitiz	zation	Category 1	H334	May cause allergy or asthma symptoms or breathing difficulties if inhaled.	
Reproductive toxic	ity	Category 2	H361d	Suspected of damaging the unborn child.	
Specific target orga	an toxicity, single exposure	Category 1	H370	Causes damage to organs: (eyes, mucous membranes).	
Specific target orga	n toxicity, repeated exposure	Category 1	H372	Causes damage to organs through prolonged or repeated exposure: (skin, respiratory tract).	
		PRECAUT	IONARY	STATEMENTS	
			PREVEN	[ION	
P201	Obtain special instructions b	efore use.			
P202	Do not handle until all safety	/ precautions hav	/e been re	ead and understood.	
P261	Avoid breathing dust/fume/gas/mist/vapors/spray.				
P264	Wash hands thoroughly after handling.				
P270	Do not eat, drink, or smoke when using this product.				
P272	Contaminated work clothing should not be allowed out of the workplace.				
P280	Wear protective gloves/protective clothing/eye protection/face protection.				
P285	In case of inadequate ventilation wear respiratory protection.				
RESPONSE					
P302+P352	IF ON SKIN: Wash with plenty of soap and water.				
P312	Call a POISON CENTER or doctor/physician if you feel unwell.				
P314	Get medical advice/attention if you feel unwell.				
P361	Remove/Take off immediately all contaminated clothing.				
P363	Wash contaminated clothing before reuse.				
P333+P313	IF SKIN irritation or rash occurs: Get medical advice/attention.				
P321	Specific treatment (as detailed on this SDS).				
P305+P351+P338	IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.				
P310	Immediately call a POISON CENTER or doctor/physician.				
P304+P341	IF INHALED: If breathing is difficult, remove victim to fresh air and keep at rest in a position comfortable for breathing.				
P342+P311	IF experiencing respiratory symptoms: call a POISON CENTER or doctor/physician.				
P307+P311	P311 IF exposed: call a POISON CENTER or doctor/physician				
			STORA	GE	
P405	Store locked up.				
	1		DISPOS		
P501	Dispose of contents/contain	er in accordance	with app	licable regional, national and local laws and regulations.	

READ THE ENTIRE SDS FOR MORE THOROUGH EVALUATION OF THE HAZARDS



CHEMICAL NAME		CAS NUMBER	% WEIGHT			
Amine curing agent		*Proprietary	100			
The specific chemical identity and exact p	percentage (concentration) is withheld as a trade secret per	applicable regulation	s and statutes.			
SECTION 4: FIRST AID MEASUR	ES					
EYE:	Get medical attention immediately. Call a poison center or physi water, occasionally lifting the upper and lower eyelids. Check for rinse for at least 10 minutes. Chemical burns must be treated pro-	r and remove any conta				
SKIN:	Get medical attention immediately. Call a poison center or physician. Wash with plenty of soap and water. Remove contaminated clothing and shoes. Wash contaminated clothing thoroughly with water before removing it, or wear gloves. Continue to rinse for at least 10 minutes. Chemica burns must be treated promptly by a physician. In the event of any complaints or symptoms, avoid further exposure. Wash clothing before reuse. Clean shoes thoroughly before reuse.					
INHALATION:	Get medical attention immediately. Call a poison center or physician. Remove victim to fresh air and keep ar rest in a position comfortable for breathing. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband. In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours. In the event of any complair or symptoms, avoid further exposure.					
INGESTION:	Get medical attention immediately. Call a poison center or physician. Wash out mouth with water. Remove dentures if any. Remove victim to fresh air and keep at rest in a position comfortable for breathing. If materia has been swallowed and the exposed person is conscious, give small quantities of water to drink. Stop if the exposed person feels sick as vomiting may be dangerous. Do not induce vomiting unless directed to do so by medical personnel. If vomiting occurs, the head should be kept low so that vomit does not enter the lung Chemical burns must be treated promptly by a physician. Never give anything by mouth to an unconscious person. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband.					
NOTES TO PHYSICIAN:	Symptomatic and supportive therapy as needed. Follow should be monitored for 48 hours.	ing severe exposure,	medical follow-up			
SECTION 5: FIRE FIGHTING MEA	SURES					
FLASH POINT:	Not available.					
HAZARDS WHEN ON FIRE OR NEAR FLAME:	In a fire or if heated, a pressure increase will occur and th	ne container may burs	t.			
SUITABLE EXTINGUISHING MEDIA:	Use an extinguishing agent suitable for the surrounding f	ïre.				
UNSUITABLE EXTINGUISHING MEDIA:	None known.					
SPECIAL EXPOSURE HAZARDS:	Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. If in a fire heated, a pressure increase will occur and the container may rupture.					
SPECIAL PROTECTIVE EQUIPMENT FOR FIRE FIGHTERS:	Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode. PVC boots, gloves safety helmet and protective clothing should be worn.					
SECTION 6: ACCIDENTAL RELEA	SE MEASURES					
ACCIDENTAL RELEASE MEASURES:	For major spills call CHEMTREC: Toll free 1-800-424-930	o for international cal	1-703-527-3887			
PERSONAL PRECAUTIONS:	Wear appropriate personal protective equipment recommended in SECTION 8: EXPOSURE CONTROL/ PERSONAL PROTECTION of this SDS. Immediately contact emergency personnel. Evacuate the area. If upwind avoiding inhalation of vapors. Clean-up should only be performed by trained personnel. People dealing with major spillages should wear full protective clothing including respiratory protection.					
ENVIRONMENTAL PRECAUTIONS:	This material may contaminate the environment without proper control and response to spills. Ensur spilled material does not come in contact with soil, waterway, drains, sewers, or other runoff that wou further disperse the material. Inform the relevant authorities if the product has caused environmenta pollution (sewers, waterways, soil, or air). Sources of ignition should be kept clear.					
METHODS FOR CONTAINMENT:	Use diking or capping to control migration. Contain and absorb large spillages with a non-flammable absorbent carrier (such as vermiculite, earth, or sand). DO NOT USE combustible materials such as sawdust Shovel into open-top drums or plastic bags for further decontamination, if necessary. Remove and properly dispose of residues. Dispose of via a licensed waste disposal contractor (See SECTION 13: DISPOSAL CONSIDERATIONS) Notify applicable government authorities if release is reportable.					
METHODS FOR CLEANING UP:	Only proceed with clean up by taking the appropriate person ensure surrounding area does not contain further hazards th or cause further harm (i.e. eliminate any ignition sources). Mo containers from the spill zone if it can be done safely. Dike, o leaks without posing further damage or harm to individuals, t Contain and collect spillage. See SECTION 13: DISPOSAL CO and SECTION 8: EXPOSURE CONTROL/ PERSONAL PROTE Protective Equipment (PPE). Obey all local, state, and federa	at could worsen the sp ove any non-contamina dam, or further restrict a he environment, and/o ONSIDERATIONS for d CTION for recommend	ill, cause migratior ited, non-leaking and stop active r structures. isposal informatior led Personal			

SECTION 7: HANDLING & STOR	AGE				
GENERAL:	Ideal storage temperature is 60-90°F (15-32°C). Handling and storage shall be in accordance with local, state/provincial, or federal regulations.				
HANDLING:	Before opening this package, read and follow warning labels on all components. Avoid contact with the product or reaction mixture. Put on appropriate personal protective equipment. Use only with adequate ventilation to ensure that the occupational exposure limit is not exceeded, use respirator when ventilation is inadequate. Avoid breathing aerosols, mists, and vapors. (See SECTION 8: EXPOSURE CONTROL/ PERSONAL PROTECTION for details). Do not ingest. Eating, drinking, and smoking shall be prohibited in areas where this material is handled, stored, and processed. Workers shall wash hands and face before eating, drinking, and smoking. Persons with a history of skin sensitization problems, asthma, allergies, or chronic or recurrent respiratory disease should not be employed in any process in which this product is used. Do not get in eyes, on skin, or clothing. Keep in the original container or an approved alternative made from a compatible material. Keep tightly closed when not in use. Empty containers retain product residue and can be hazardous. Do not reuse containers.				
STORAGE:	Keep container tightly closed and properly sealed when stored. When possible, store product indoors in a dry, well-ventilated area. Store in original container, away from incompatible materials, and away from food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers and use appropriate containment to avoid environmental contamination.				
SECTION 8: EXPOSURE CONTR	OLS/PERSONAL PROTECTION				
EXPOSURE LIMITS:	As of the latest revision of this document, no known exposure limits exist for this product. The absence of current exposure data does not relieve an employer, user, or other to determine the specific hazards and appropriate exposure protection measures in the application and use of this product. Personal, workplace, atmospheric, and/or biological monitoring may be required to determine the effectiveness of engineering, administrative, and/or other best practice control measures. These monitoring results determine the need for and type of respiratory protective equipment, if any. Refer to the appropriate local, state, and federal regulations and statutes for the most current information and for guidance in the determination of hazardous conditions and the correlating personal protective equipment.				
ENGINEERING CONTROLS:	Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor, or mist, use process enclosures, local exhaust ventilation, and other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits.				
HYGIENE MEASURES:	Wash hands, forearms, and face thoroughly with plenty of soap and water after handling chemical products, before eating, smoking, and using the restroom and at the end of the working period. Appropriate engineering, administrative, and other best practice decontamination control measures must be used to isolate contaminates on clothing and to prevent unintended migration of contaminants. Handle clothing and other potentially contaminated material appropriately and in compliance with local, state, and federal regulations in the process of removing, washing/cleaning, and reuse of these potentially contaminated materials. Ensure compliant use and location of eyewash station and safety showers.				
PERSONAL PROTECTIVE EQUIPMENT (PPE):				
EYE PROTECTION:	Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: chemical splash goggles and/or face shield.				
SKIN PROTECTION:	Personal protective equipment for the body should be selected based on the task being performed, the risks involved, and should be approved by an industrial hygiene specialist before handling this product.				
HANDS PROTECTION:	Chemical resistant gloves complying with applicable health and safety standards shall be worn when handling this product. Protective gloves are those made from butyl rubber, nitrile rubber, or polyvinyl alcohol. Appropriate hazard assessments in conjunction with an evaluation of the protection factors of chemical resistant gloves shall be performed to ensure the protective properties remain intact. It is noted that the time it takes to breakdown of protection factors of chemical resistant gloves may be impacted and deteriorate at unpredictable rates without understanding the impact of the substance and the specific protection factors of the chemical resistant gloves.				
RESPIRATORY PROTECTION:	Ensure adequate ventilation. If the respirator is the sole means of protection, use a full-face supplied respirator. Use respirators and components tested and approved under appropriate government standards such as OSHA 29CFR 1910.134, NIOSH (US), or CEN (EU).				
ENVIRONMENTAL EXPOSURE CONTROLS:	Dispose of raw and spent materials and wastes in compliance with all local, state, and federal regulations to prevent potential environmental contamination. Industrial air monitoring may be required to determine any potential environmental hazards to the atmosphere. This monitoring may result in the use of engineering and administrative controls such as filtering and scrubbing systems to mitigate or eliminate potential contaminants.				

SECTION 9: PHYSICAL & C	HEMICAL PROPERT	IES					
PHYSICAL STATE:	Liquid	FLASH POINT	:	Not available			
COLOR:	Amber	AUTO-IGNITIC	ON TEMPERATURE:	Not available			
ODOR:	Amine odor	DECOMPOSIT	TION TEMPERATURE:	Not available			
ODOR THRESHOLD:	Not available	EXPLOSIVE L	IMITS:	Not explosive			
pH:	Not applicable	FLAMMABILI	ΓY:	Not available			
WATER SOLUBILITY:	Not available	BOILING POIN	NT:	Not available			
PARTITION COEFFICIENT:	Not available	BOILING RAN	GE:	Not available			
SPECIFIC GRAVITY:	1.01±0.005 g/cc @ 77°F (2	25°C) MELTING/FRE	EZING POINT:	Not available			
VISCOSITY:	150±25 mPa.s @ 77°F (25	°C) VAPOR PRES	SURE:	Not available			
EVAPORATION RATE:	Not available	VAPOR DENS	ITY:	Not available			
VOC:	0 g/L	RELATIVE DE	NSITY:	8.4±0.05 lbs/gal			
SECTION 10: STABILITY &	REACTIVITY						
STABILITY:	Stable under normal con	ditions.					
INCOMPATIBILITY:	Avoid strong oxidizing ag	gents.					
HAZARDOUS REACTION:	Under normal conditions	of storage and use, haza	ardous reactions will not o	ccur.			
HAZARDOUS POLYMERIZATION:	Not available.						
CONDITIONS TO AVOID:	Avoid strong oxidizers and	d keep away from heat, spa	arks, flame and other ignitio	n sources.			
HAZARDOUS DECOMPOSITION:	Combustion of product wi	II lead to oxides of nitroger	n, carbon dioxide, and carbo	n monoxide being produced.			
SECTION 11: TOXICOLOGY	INFORMATION						
ACUTE HEALTH EFFECTS:							
EYE CONTACT:	Causes serious eye damage.						
SKIN CONTACT:	Harmful in contact with skin. May cause an allergic skin reaction.						
INHALATION:	May give off gas, vapour or dust that is very irritating or corrosive to the respiratory system. May cause allergy or asthma symptoms or breathing difficulties if inhaled. Exposure to decomposition products may cause a health hazard. Serious effects may be delayed following exposure.						
INGESTION:	Not available.						
ACUTE TOXICITY:							
COMPONENT NAME	CAS NUMBER	LD ₅₀ Oral (mg/kg)	LD ₅₀ Dermal (mg/kg)	LC ₅₀ Inhalation (mg/L/4hrs)			
Amine curing agent	*Proprietary	Not available	Not available	Not available			
POTENTIAL CHRONIC EFFECTS:	· ·						
CHRONIC EFFECTS:	Causes damage to organs through prolonged or repeated exposure: Once sensitized, a severe allergic reaction may occur when subsequently exposed to very low levels.						
TARGET ORGANS:	Respiratory tract.						
CARCINOGENICITY:	No known significant effects or critical hazards.						
MUTAGENICITY:	No known significant effects or critical hazards.						
TERATOGENICITY:	Suspected of damaging the unborn child.						
	No known significant effects or critical hazards.						
FERTILITY EFFECTS:	Ho known significant ch		No known significant effects or critical hazards.				
FERTILITY EFFECTS: DEVELOPMENTAL EFFECTS:							
DEVELOPMENTAL EFFECTS: MEDICAL CONDITIONS AGGRAVATED BY	No known significant eff Not available.						
DEVELOPMENTAL EFFECTS: MEDICAL CONDITIONS AGGRAVATED BY OVER-EXPOSURE:	No known significant eff Not available.	ects or critical hazards.					

SECTION 13: DISPOSAL CONSIDERATION				
WASTE DISPOSAL:	By-product wastes or process waste generation should be eliminated and/or minimized when possible. Do not dispose of any contaminants into sanitary sewer systems, storm drains, Publicly Owned Treatment Works (POTW), or any other municipal waste water treatment facility without written approval and agreements for processing wastes with such enterprises. Dispose of raw or unused materials, wastes, and/or by-products in accordance with all applicable local, state, and federal laws. Employ the expertise and knowledge of qualified personnel or contractors in disposal of any and all variants of this product. Ensure material containers are cleaned to the applicable standards before recycling, disposing, or reusing containers. Take special precautions to avoid any cross contamination and potential unknown effects from mixing with other substances. Refer to SECTION 8: EXPOSURE CONTROL/ PERSONAL PROTECTION of this document for personal protection requirements. Disposal to the environment or in violation of environmental protection laws and statutes must be prevented.			

SECTION 14: TRANSPORT INFORMATION

PROPER SHIPPING NAME

DOT:	Corrosive liquid, n.o.s. (Polyamidoamine, Aliphatic amine)			
TDG:	Corrosive liquid, n.o.s. (Polyamidoamine, Aliphatic amine)			
IMDG:	Corrosive liquid, n.o.s. (Polyamidoamine, Aliphatic amine)			
IATA:	Corrosive liquid, n.o.s. (Polyamidoamine, Aliphatic amine)			

This product could potentially contaminate aquatic and terrestrial environments if not handled in accordance with all precautions, regulations, and laws. Users, transporters, and all other applicable entities must review, follow, and apply any and all necessary precautions and procedures to eliminate and/or minimize potential hazards or risks to aquatic or terrestrial environments.

REGULATORY INFORMATION	UN NUMBER	CLASSES	PG*	LABEL	ADDITIONAL INFORMATION
DOT Classification	UN2735	8	=	CORROSIVE 8	None
TDG Classification	UN2735	8	111		Marine Pollutant
IMDG Classification	UN2735	8	111		Marine Pollutant
IATA-DGR Classification	UN2735	8	111		Passenger and Cargo Aircraft Quantity limitation: 1 L Packaging Instructions: 852 Cargo Aircraft Only Quantity limitation: 60 L Packaging Instructions: 856 Marine Pollutant
*PG: Packaging group	*PG: Packaging group				

SECTION 15: REGULATORY INF	ORMATION
U.S. FEDERAL REGULATIONS	
TSCA 8b Inventory:	All components are listed on the TSCA inventory or are exempt.
TSCA 5a (2):	No components listed.
TSCA 5e:	No components listed.
TSCA 12b:	No components listed.
Clean Air Act Section 112(b) Hazardous Air Pollutants (HAPs):	No components listed.
Clean Air Act - Ozone Depleting Substances (ODS):	This product does not contain nor is it manufactured with ozone depleting substances.
SARA 313 Form R - Reporting Requirements:	No components listed.
SARA 311/312 hazard identification:	Immediate (acute) health hazard.
CERCLA Hazardous substances:	No components listed.
STATE REGULATIONS:	
PENNSYLVANIA/NEW JERSEY/ MASSACHUSETTS - RTK:	No components listed.
California Prop 65:	This product contains no listed substances known to the State of California to cause cancer, birth defects, or other reproductive harm, at levels which would require a warning under the statute.
CANADA	
WHMIS (Canada):	WHMIS Class D-1B: Material causing immediate and serious toxic effects (toxic). WHMIS Class D-2A: Material causing other toxic effects (Very toxic). WHMIS Class D-2B: Material causing other toxic effects (Toxic).
CEPA DSL:	All components are listed or exempted.
This product has been classified in acco the information required by the Controll	rdance with the hazard criteria of the Controlled Products Regulations and the SDS contains all ed Products Regulations.
INTERNATIONAL LISTS:	
Australia inventory (AICS):	All components are listed or exempted.
China inventory (IECSC):	All components are listed or exempted.
Japan inventory:	All components are listed or exempted.
Korea inventory:	All components are listed or exempted.
New Zealand inventory of Chemicals (NZIoC):	All components are listed or exempted.
Phillipines inventory (PICCS):	All components are listed or exempted.

SECTION 16: OTHER INFORMATION



Note: The customer is responsible for determining the PPE code for this material. At the time of publishing, the NFPA/HMIS and the New GHS scale had opposite scales of severity. Check the most recent publications for current information.

For Your Protection:	The information and recommendations in this publication is to the best of our knowledge, reliable. The toxicity and risk characteristics of products made by SPI will necessarily differ from the toxicity and risk characteristics that occur when such products are used with other materials during a manufacturing process. The resulting risk characteristics should be determined and made known to ultimate end-users and processors. The user is responsible to comply with all applicable federal, provincial or municipal laws and regulations. SPI MAKES NO WARRANTIES OF ANY KIND, EXPRESSED OR IMPLIED, INCLUDING THOSE OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.
Preparation Information:	This SDS supersedes ALL previous SDS versions.